



m/c /050

United States Department of the Interior

BUREAU OF LAND MANAGEMENT

3809
(U-068)

Moab District
Grand Resource Area
P. O. Box M
Moab, Utah 84532

OCT 6 1989

Mr. Holland Shepherd
Utah Department of Natural Resources
Division of Oil, Gas and Mining
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203

Re: Final Reclamation/Bond Readjustment for the Red Rock Mine Site,
San Juan County, Utah

Dear Mr. Shepherd:

On September 5, 1989 a member of my staff checked on the progress of reclamation by Mr. Clayton Stocks, prior operator at the Red Rock Mine site, located in T28S, R23E (SLM), Sections 26 and 27. Inspection was made for the surface reclamation only. The inspector was not present when the mine shaft, vent holes and drill holes were sealed. Surface reclamation has been completed and appears to be satisfactory.

Based on Mr. Stock's efforts, I would recommend readjustment of the existing bond. As you and I discussed, a portion of the bond needs to remain in effect until the reseeding efforts are deemed acceptable.

If you have additional questions concerning what was observed during the final inspection, please contact Sal Venticinque at (801) 259-8193.

Sincerely yours,

Brad D. Palmer
Area Manager